

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080124-6

No. 11059

RECEIVED FROM

Plant #9

DATE REC'D 1-24-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DATE OF STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
1	322	000000	20013							738319-2 22053 Bearing Retainer to superseded 211029

W. P. Parker
D. E. Parker

RECEIVED BY
HMC-1089

INSPECTED BY

DATE 1/28/57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

251 E. COLORADO ST., PASADENA, CALIF.

No. 11064

RECEIVED FROM

Plant #9

DATE REC'D 1-2-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DATE OF STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
1	322	000000	20013							738263 Wiring Assy to superseded 21101

W. P. Parker
D. E. Parker

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080124-6

RECEIVED BY

HMC-1089

REJECTS RETURNED